



"JAWORSKI, MARK"
<MJAWORSK@idem.IN.gov>

06/10/2008 08:15 AM

To LAURA RIPLEY/R5/USEPA/US@EPA

cc

bcc

Subject

EPA Region 5 Records Ctr.



309323

Laura,

In my 6-9-08 e-mail to you regarding a review of Sanborn Maps that I conducted to determine if there are any other potential sources of lead near the former USS Lead facility that may have adversely impacted the surrounding soils, I did not include two Sanborn Maps that depict the Glidden Co.; Metals Refining. Inc. Division. Attached are two Sanborn maps that depict the Glidden facility in 1930 and 1939. As stated in the original e-mail, both of these maps are available at the Indiana State Library located in Indianapolis, Indiana.




Mark Jaworski USS Lead Sanborn Maps 2.pdf

001

REFERENCE # 114

1939
p. 305

Sanborne maps 1939



RIC CASTEEL CO.
CASTINGS:

FINISHING RM. & MACHINE SHOP
STEEL FRAME

VDRY

WATCHMEN
& POWER! ELEC:

1930

P. 385

VACANT
RAISED 2' ON
CONC. PIER

148

Sanborn maps
1930

HUMP

RD

REFUNING
RECLAIMING

OXIDE STORAGE
METAL

OXIDIZING
PLANT

STORAGE

~~ST. PLN~~
~~8 OFFIC~~

1

WATCHMAN - NO CLOCK - HEAT/STERN
LIGHTS & POWER/ELEC CITY WATER
300-274056

SUMMER

BLVD.

12" W. PIPE

4" W. PIPE

127W. PIP

PLATEFORM
YARD
WOOD PLAYING

70

R.D.

— 1 —

1000

[REDACTED]